

Stream Assessment Summary Form (Form 2)

Unified Stream Methodology for use in Virginia

Project #	Applicant	Date
2017-890	Green Ridge Recycling and Disposal Facility	4/11/2022
Evaluators	HUC	Locality
David Kwasniewski, PWD, Kristen Walls, WPIT, Emily Beacham, PE, Eric Myers, Hannah Bullens	02080205	Cumberland Co.

Stream Name	Reach ID	Length of Impact (L ₁) (feet)	Reach Condition Index (RCI)	Impact Factor (IF)	Compensation Requirement (CR) (L ₁ × RCI × IF)
Reach 1	Impact 1.1	915	1.38	1	1,263
Reach 1	Impact 1.2	60	0.66	1	40
Reach 1	Impact 1.3	181	1.18	1	214
Reach 1	Impact 1.4	352	1.38	1	486
Reach 1	Impact 1.5	66	0.75	1	50
Reach 1	Impact 1.6	68	1.26	1	86
Reach 1	Impact 1.7	143	0.75	1	107
Reach 1	Impact 1.8	59	0.75	1	44
Reach 2	Impact 2.1	1,391	1.32	1	1,836
Reach 2	Impact 2.2	1,066	1.32	1	1,407
Reach 2	Impact 2.3	136	0.75	1	102
Reach 2	Impact 2.4	377	1.26	1	475
Reach 2	Impact 2.5	142	0.69	1	98
Reach 3	Impact 3.1	302	1.13	1	341
Reach 3	Impact 3.2	331	1.15	1	381
Reach 3	Impact 3.3	475	0.52	1	247
Reach 3	Impact 3.4	266	0.59	1	157
Reach 3	Impact 3.5	300	1.26	1	378
Reach 3	Impact 3.6	184	0.46	1	85
Reach 4	Impact 4.1	77	1.11	1	85
Reach 4	Impact 4.1 Sec.	192	1.15	1	221
Reach 4	Impact 4.2	518	1.25	1	648
Reach 4	Impact 4.3	186	0.43	1	80
Reach 5	Impact 5.1	300	1.17	1	351
Reach 5	Impact 5.1 Sec.	134	1.10	1	147
Reach 5	Impact 5.2	131	1.05	1	138
Reach 5	Impact 5.3	155	0.43	1	67
Reach 5	Impact 5.4	179	1.19	1	213
Reach 5	Impact 5.5	206	0.43	1	89
Reach 6	Impact 6.1	326	1.31	1	427
Reach 7	Impact 7.1	363	1.21	1	439
Reach 7	Impact 7.1 Sec.	83	1.23	1	102
Reach 8	Impact 8.1	132	0.49	1	65
Reach 9	Impact 9.1	263	1.44	1	379
Reach 9	Impact 9.1 Sec.	59	1.44	1	85
Reach 9	Impact 9.2	106	1.26	1	134
Reach 9	Impact 9.3	128	0.75	1	96
	Impact RR.1	123	1.24	1	153
	Impact RR.2	166	1.32	1	219
	Impact RR.3	149	1.34	1	200
	Impact EW.1	124	1.21	1	150
	Impact EW.2	195	1.23	1	240
	Impact EW.3	77	1.18	1	91
	Impact EW.4	80	1.24	1	99
	Impact EW.5	239	1.24	1	296
	Impact EW.6	132	0.75	1	99
	Total L₁	11,637		Total CR	13,106

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/25/2022	Impact 1.1	915	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Eric Myers	Stream Reach 1 - Impact Plate C1.1/Impact 1.1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>>	Minimal erosion along meander.
---------	--------------------------------

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Easement located within portion of riparian buffer. Pine Forest dominated both left and right bank. Hardwood understory observed.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
		High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	100%						100%
	Score >	1.5						
Left Bank	% Riparian Area>	100%						100%
	Score >	1.5						

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Varying velocity in stream flow. Needle and leaf pack present. Minimal amount of woody debris.

CI
1.50

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor	
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/25/2022	Impact 1.1	915	1	
4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock							NOTES>> No alternative to the reach was observed.		
Channel Alteration	Conditional Category								
	Negligible	Minor		Moderate		Severe			
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.			
	SCORE	1.5	1.3	1.1	0.9	0.7			0.5
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH							1.50		
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.							THE REACH CONDITION INDEX (RCI) >>		1.38
							RCI= (Sum of all CI's)/5		
							COMPENSATION REQUIREMENT (CR) >>		1263
							CR = RCI X LF X IF		

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	3/28/2022	Impact 1.2	60	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beacham, PE		Stream Reach 1 - Impact Plate C1.1/Impact 1.2						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Channel interrupted by headcut/clearing of relic roadway, historic rutting observed. Holding water - possibly from precipitation.
	Optimal	Suboptimal	Marginal	Poor				
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
Condition Scores	1.5	High 1.2 Low 1.1	High 0.85 Low 0.75	High 0.6 Low 0.5				
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.								Ensure the sums of % Riparian Blocks equal 100
Right Bank	% Riparian Area> 70% Score > 1.5	30% 0.85					100%	
Left Bank	% Riparian Area> 70% Score > 1.5	30% 0.85					100%	
CI= (Sum % RA * Scores*0.01)/2 Rt Bank CI > 1.31 Lt Bank CI > 1.31								CI 1.31
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.								THE REACH CONDITION INDEX (RCI) >> 0.66 RCI= (Riparian CI)/2 COMPENSATION REQUIREMENT (CR) >> 40 CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	3/28/2022	Impact 1.3	181	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Emily Beacham, PE	Stream Reach 1 - Impact Plate C1.1/Impact 1.3

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>>	Floodplain benches present, but not active. Stream channel defined but not incised.
---------	---

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Pine forest hardwood understory.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
		High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	100%						100%
	Score >	1.5						
Left Bank	% Riparian Area>	100%						100%
	Score >	1.5						

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				NOTES>> Very little water with minimal changes in velocity, limited vegetation in particle size, channel lacks undercut banks/woody debris, areas of leaf pack observed.	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		0.90

Unified Stream Methodology for use in Virginia

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/25/2022	Impact 1.4	352	1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Conditional Category

NOTES>>	Several bedrock grade controls observed through the reach. Minimal erosion observed along outer meander.
---------	--

Conditional Category

NOTES>> Pine forest
hardwood understory.

- Ensure the sums
of % Riparian
Blocks equal 100


Rt Bank CI >	1.50	CI
Lt Bank CI >	1.50	1.50

NOTES>> Fluctuations in velocity observed. Woody debris and leaf pack was also observed.

CI
1.50

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor	
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/25/2022	Impact 1.4	352	1	
4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock							NOTES>> No alterations to the reach was observed.		
Channel Alteration	Conditional Category								
	Negligible	Minor		Moderate	Severe				
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.			
	SCORE	1.5	1.3	1.1	0.9	0.7			0.5
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH							1.50		
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.							THE REACH CONDITION INDEX (RCI) >>		1.38
							RCI= (Sum of all CI's)/5		
							COMPENSATION REQUIREMENT (CR) >>		486
							CR = RCI X LF X IF		

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	3/28/2022	Impact 1.5	66	1

Name(s) of Evaluator(s)

David Kwasniewski, PWD and Emily Beacham, PE

Stream Name and Information

Stream Reach 1 - Impact Plate C1.1/Impact 1.5

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Mature hardwood / pine forest on both sides.
Riparian Buffers	Optimal	Suboptimal	Marginal	Poor				
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory . Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh >3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100		
Right Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
Left Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
							CI= (Sum % RA * Scores*0.01)/2	
						Rt Bank CI >	1.50	CI
						Lt Bank CI >	1.50	1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 0.75

RCI= (Riparian CI)/2

COMPENSATION REQUIREMENT (CR) >> 50

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	3/25/2022	Impact 1.6	68	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Eric Myers	Stream Reach 1 - Impact Plate C1.1/Impact 1.6

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>>	Minimal erosion observed.
---------	---------------------------

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Pine forest hardwood understory.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
		High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	100%					100%
	Score >	1.5					
Left Bank	% Riparian Area>	100%					100%
	Score >	1.5					
						Rt Bank CI >	1.50
						Lt Bank CI >	1.50

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Two pools in reach. Very little velocity variation.

CI

0.90

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor	
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	3/25/2022	Impact 1.6	68	1	
4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock							NOTES>> No alteration to the reach was observed.		
Channel Alteration	Conditional Category								
	Negligible	Minor		Moderate		Severe			
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.			
	SCORE	1.5	1.3	1.1	0.9	0.7			0.5
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH							1.50		
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.							THE REACH CONDITION INDEX (RCI) >>		1.26
							RCI= (Sum of all CI's)/5		
							COMPENSATION REQUIREMENT (CR) >>		86
							CR = RCI X LF X IF		

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	3/25/2022	Impact 1.7	143	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Eric Myers		Stream Reach 1 - Impact Plate C1.1/Impact 1.7						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Pine forest Hardwood understory.
Riparian Buffers	Optimal	Suboptimal	Marginal	Poor				
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained (understory).	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
		Condition Scores	High	Low	High	Low	High	
	1.5	1.2	1.1	0.85	0.75	0.6	0.5	
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.								Ensure the sums of % Riparian Blocks equal 100
Right Bank	% Riparian Area>	100%						100%
	Score >	1.5						
Left Bank	% Riparian Area>	100%						100%
	Score >	1.5						
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								CI= (Sum % RA * Scores*0.01)/2 Rt Bank CI > 1.50 Lt Bank CI > 1.50 CI

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 0.75

RCI= (Riparian CI)/2

COMPENSATION REQUIREMENT (CR) >> 107

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	3/28/2022	Impact 1.8	59	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beachman, PE		Stream Reach 1 - Impact Plate C1.1/Impact 1.8						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Dominated mostly by pines.			
	Optimal	Suboptimal	Marginal	Poor							
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.				
		High	Low	High	Low	High	Low				
Condition Scores	1.5	1.2 1.1	0.85 0.75	0.6 0.5							
<p>1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.</p> <p>2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.</p> <p>3. Enter the % Riparian Area and Score for each riparian category in the blocks below.</p>								Ensure the sums of % Riparian Blocks equal 100			
Right Bank	% Riparian Area>	100%					100%				
	Score >	1.5									
Left Bank								CI= (Sum % RA * Scores*0.01)/2			
	% Riparian Area>	100%					100%	Rt Bank CI >	1.50	CI	
	Score >	1.5						Lt Bank CI >	1.50	1.50	
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH											
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.										THE REACH CONDITION INDEX (RCI) >>	0.75
										RCI= (Riparian CI)/2	
										COMPENSATION REQUIREMENT (CR) >>	44
										CR = RCI X LF X IF	

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal areas.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/28/2022	Impact 2.1	1,391	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Emily Beacham, PE	Stream Reach 2 - Impact Plate C1.2/Impact 2.1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Some erosion on outer meanders. Bedrock as grade control, more cobbles observed than intermittent portion of reach.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Easement located within portion of riparian buffer.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
		High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	100%					100%
	Score >	1.5					
Left Bank	% Riparian Area>	100%					100%
	Score >	1.5					

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Fluctuations in velocity, leaf pack. Woody debris observed, cobbles in riffle.

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/28/2022	Impact 2.1	1,391	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations were observed.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.32

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

1836

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	3/28/2022	Impact 2.2	1,066	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Emily Beacham, PE	Stream Reach 2 - Impact Plate C1.2/Impact 2.2

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Upstream of 2.1 and downstream of 2.3.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> somewhat open understory, hardwood forest.
Riparian Buffers	Optimal	Suboptimal		Marginal		Poor		
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh >3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
			High	Low	High	Low	High	
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100		
Right Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
Left Bank	% Riparian Area>	100%					100%	
	Score >	1.5						

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	3/28/2022	Impact 2.2	1,066	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alteration has been made.

Channel Alteration	Conditional Category					
	Negligible	Minor		Moderate		Severe
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7	0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.32

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

1407

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	3/28/2022	Impact 2.3	136	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beacham, PE		Stream Reach 2 - Impact Plate C1.2/Impact 2.3						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Somewhat open understory, otherwise hardwood forest-tulip popular.
	Optimal	Suboptimal	Marginal	Poor				
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
Condition Scores	1.5	High 1.2 Low 1.1	High 0.85 Low 0.75	High 0.6 Low 0.5				
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.								Ensure the sums of % Riparian Blocks equal 100
Right Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
Left Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.								
THE REACH CONDITION INDEX (RCI) >>								0.75
RCI= (Riparian CI)/2								
COMPENSATION REQUIREMENT (CR) >>								102
CR = RCI X LF X IF								

INSERT PHOTOS:



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/1/2022	Impact 2.4	377	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Emily Beacham, PE	Stream Reach 2 - Impact Plate C1.2/Impact 2.4

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Channel does not have access to a floodplain. Little to no erosion observed, no downcutting or incision or aggradation.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						Condition Scores	NOTES>> Mature pine forest with hardwood understory.
	Optimal	Suboptimal	Marginal	Poor	High	Low		
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	100%						100%
	Score >	1.5						
Left Bank	% Riparian Area>	100%						100%
	Score >	1.5						

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Middle portion of reach (w/ water) had habitat elements, upslope and downslope had no habitat.

CI

0.90

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/1/2022	Impact 2.4	377	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alteration has been made.

Channel Alteration	Conditional Category					
	Negligible	Minor		Moderate		Severe
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7	0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.26

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

475

CR = RCI X LF X IF

INSERT PHOTOS



DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/1/2022	Impact 2.5	142	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beacham, PE		Stream Reach 2 - Impact Plate C1.2/Impact 2.5						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Recently cleared and regrown with pine. Young and small for upstream buffer. Downstream portion of reach has tree buffer.	
Optimal	Suboptimal		Marginal		Poor				
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.		
		Condition Scores	High	Low	High	Low	High		
	1.5	1.2	1.1	0.85	0.75	0.6	0.5		
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.								Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	60%	40%					100%	
	Score >	1.5	1.2						
Left Bank	% Riparian Area>	60%	40%					100%	
	Score >	1.5	1.2						
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								CI= (Sum % RA * Scores*0.01)/2 Rt Bank CI > 1.38 Lt Bank CI > 1.38 CI	
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.								THE REACH CONDITION INDEX (RCI) >> RCI= (Riparian CI)/2 COMPENSATION REQUIREMENT (CR) >> CR = RCI X LF X IF	
								0.69 98	

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	4/1/2022	Impact 3.1	302	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Emily Beacham, PE	Stream Reach 3 - Impact Plate C1.3/Impact 3.1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>>	DS impact of 3.4, channel does not have well-defined bed+bank. Many grade contours observed. Erosion and vertical banks near confluence of 3.4 and US, up to 4 feet vertical banks near confluence with main channel (DS).
---------	--

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						Condition Scores	NOTES>> Some previously cleared areas in buffer, now overgrown.
	Optimal	Suboptimal	Marginal	Poor	High Suboptimal:	Low Suboptimal:		
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
		High	Low	High	Low	High	Low	
	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	80%	20%					100%
	Score >	1.5	0.85					
Left Bank	% Riparian Area>	80%	20%					100%
	Score >	1.5	0.85					

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pool complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Pools, leaf-pack, woody debris.

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	4/1/2022	Impact 3.1	302	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alteration.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .
SCORE	1.5	1.3	1.1	0.9	0.7

SCORE 1.5 1.3 1.1 0.9 0.7 0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.13

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

341

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/1/2022	Impact 3.2	331	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alteration.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.15

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

381

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/1/2022	Impact 3.3	475	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beacham, PE		Stream Reach 3 - Impact Plate C1.3/Impact 3.3						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Left bank was recently cleared with trees and right bank was recently cleared with very few trees.
Riparian Buffers	Optimal	Suboptimal	Marginal	Poor				
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
Condition Scores	1.5	High 1.2 Low 1.1	High 0.85 Low 0.75	High 0.6 Low 0.5				
<p>1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.</p> <p>2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.</p> <p>3. Enter the % Riparian Area and Score for each riparian category in the blocks below.</p>								
Right Bank	% Riparian Area>	100%					100%	
	Score >	1.2						
Left Bank	% Riparian Area>	100%					100%	
	Score >	0.85						
<p>CI= (Sum % RA * Scores*0.01)/2</p> <p>Rt Bank CI > 1.20</p> <p>Lt Bank CI > 0.85</p>								
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 0.52

RCI= (Riparian CI)/2

COMPENSATION REQUIREMENT (CR) >> 247

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/1/2022	Impact 3.4	266	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beacham, PE		Stream Reach 3 - Impact Plate C1.3/Impact 3.4						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Previously cleared area in state of regrowth.	
Optimal	Suboptimal		Marginal		Poor				
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.		
		Condition Scores	1.5	High 1.2 Low 1.1	High 0.85 Low 0.75	High 0.6 Low 0.5			
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.								Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	50%	50%					100%	
	Score >	1.5	0.85						
Left Bank	% Riparian Area>	50%	50%					100%	
	Score >	1.5	0.85						
CI= (Sum % RA * Scores*0.01)/2 Rt Bank CI > 1.18 Lt Bank CI > 1.18									
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.									
THE REACH CONDITION INDEX (RCI) >>								0.59	
RCI= (Riparian CI)/2									
COMPENSATION REQUIREMENT (CR) >>								157	
CR = RCI X LF X IF									

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/1/2022	Impact 3.5	300	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Emily Beacham, PE	Stream Reach 3 - Impact Plate C1.3/Impact 3.5

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Some steep, but low banks (less than 1 foot).

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Left bank was recently cleared with trees and right bank was recently cleared with very few trees.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
		High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	20%	80%					100%
	Score >	1.2	0.85					
Left Bank	% Riparian Area>	20%	80%					100%
	Score >	1.2	0.85					

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				NOTES>> Undercut banks, pools were observed.	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		1.50

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/1/2022	Impact 3.5	300	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alteration.

Channel Alteration	Conditional Category					
	Negligible	Minor	Moderate	Severe		
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7	0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.26

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 378

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/1/2022	Impact 3.6	184	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beacham, PE		Stream Reach 3 - Impact Plate C1.3/Impact 3.6						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Left bank was recently cleared with trees and right bank was recently cleared with very few trees.
Riparian Buffers	Optimal	Suboptimal	Marginal	Poor				
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
Condition Scores	1.5	High 1.2	Low 1.1	High 0.85	Low 0.75	High 0.6	Low 0.5	
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100		
Right Bank	% Riparian Area>	20%	80%				100%	
	Score >	1.2	0.85					
Left Bank	% Riparian Area>	20%	80%				100%	
	Score >	1.2	0.85					
CI= (Sum % RA * Scores*0.01)/2								
Rt Bank CI > 0.92								
Lt Bank CI > 0.92								
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 0.46

RCI= (Riparian CI)/2

COMPENSATION REQUIREMENT (CR) >> 85

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	4/6/2022	Impact 4.1	77	1

Name(s) of Evaluator(s)	Stream Name and Information
Kristen Walls, WPIT, Emily Beacham, PE and Hannah Bullens	Stream Reach 4 - Impact Plate C1.4/Impact 4.1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
Score	3	2.4	2	1.6	1		2.0

NOTES>>	Erosion present on 40% of banks.
---------	----------------------------------

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Left bank and right bank prominently young hardwoods.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.	Ensure the sums of % Riparian Blocks equal 100
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.	
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.	

Right Bank	% Riparian Area>	100%					100%
	Score >	0.85					

Left Bank	% Riparian Area>	100%					100%
	Score >	0.85					

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				NOTES>> Some leaf packs present.	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	4/6/2022	Impact 4.1	77	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category					
	Negligible	Minor	Moderate	Severe		
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7	0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.11

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

85

CR = RCI X LF X IF

INSERT PHOTOS



DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	4/6/2022	Impact 4.1 Sec.	192	1

Name(s) of Evaluator(s)	Stream Name and Information
Kristen Walls, WPIT, Emily Beacham, PE and Hannah Bullens	Stream Reach 4 - Impact Plate C1.4/Impact 4.1 Sec.

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
Score	3	2.4	2	1.6	1		2.0

NOTES>>	Poor condition upstream 60%, suboptimal downstream 40%.
---------	---

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						Condition Scores	NOTES>> The right bank is a young hardwood forest. The left bank has some large trees but <60% canopy.
	Optimal	Suboptimal	Marginal	Poor	High	Low		
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
		High	Low	High	Low	High	Low	
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.	Ensure the sums of % Riparian Blocks equal 100
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.	
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.	

Right Bank	% Riparian Area>	100%						100%
	Score >	0.85						
Left Bank	% Riparian Area>	100%						100%
	Score >	1.2						

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		1.20

NOTES>> Limited changes in flow velocity, no undercut banks.

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	4/6/2022	Impact 4.1 Sec.	192	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .
SCORE	1.5	1.3	1.1	0.9	0.7

	1.50
--	-------------

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.15

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 221

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/6/2022	Impact 4.2	518	1

Name(s) of Evaluator(s)






[illegible]

Kristen Walls, WPIT, Emily Beacham, PE and Hannah Bullens

Stream Reach 4 - Impact Plate C1.4/Impact 4.2

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Conditional Category	Count	Percentage
1	1	100%

	Optimal	Suboptimal	Marginal	Poor	Severe
Channel Condition	 <p>Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.</p>	 <p>Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.</p>	 <p>Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which</p>	 <p>Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent</p>	 <p>Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.</p>
Score	3	2.4	2	1.6	1

CI

NOTES>>

Intermittent stream; bankfull indicators weak.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category

Riparian Buffers	Optimal	Suboptimal		Marginal		Poor		hardwood forest.
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory . Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
		High	Low	High	Low	High	Low	
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

NOTES>> Young
hardwood forest.

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.

Ensure the sums
of % Riparian
Blocks equal 100

Right Bank	% Riparian Area>	100%						100%		
	Score >	0.85								
Left Bank	% Riparian Area>	100%						100%	Rt Bank CI >	0.85
	Score >	0.85							Lt Bank CI >	0.85

NOTES>> Woody and leafy debris present, 2 frogs.

CI

0.90

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact 4.2	518	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .
					Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
	SCORE	1.5	1.3	1.1	0.9

								1.50
--	--	--	--	--	--	--	--	-------------

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.25

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 648

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/6/2022	Impact 4.3	186	1

Name(s) of Evaluator(s)	Stream Name and Information
Kristen Walls, WPIT, Emily Beacham, PE and Hannah Bullens	Stream Reach 4 - Impact Plate C1.4/Impact 4.3

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Young hardwood forest.					
Optimal	Suboptimal		Marginal		Poor								
Riparian Buffers Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.							
							High		Low	High	Low	High	Low
							Condition Scores		1.5	1.2	1.1	0.85	0.75

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	100%						100%
	Score >	0.85						

CI= (Sum % RA * Scores*0.01)/2

Left Bank	% Riparian Area>	100%						100%
	Score >	0.85						

Rt Bank CI > 0.85
Lt Bank CI > 0.85

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 0.43

RCI= (Riparian CI)/2

COMPENSATION REQUIREMENT (CR) >> 80

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Unified Stream Methodology for use in Virginia

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/6/2022	Impact 5.1	300	1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

	Optimal	Suboptimal	Marginal	Poor	Severe
1. Overall					
2. Prevalence					
3. Incidence					
4. Duration					
5. Prognosis					
6. Quality of life					
7. Healthcare costs					
8. Social costs					
9. Economic costs					
10. Environmental costs					
11. Policy costs					
12. Legal costs					
13. Administrative costs					
14. Research costs					
15. Education costs					
16. Prevention costs					
17. Treatment costs					
18. Rehabilitation costs					
19. End-of-life costs					
20. Other costs					

NOTES					
-------	--	--	--	--	--

[illegible]

Conditional Category	NOTES>> Some
----------------------	--------------

1	Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the	
---	--	--

	% Riparian Area>	80%	20%					100%
--	------------------	-----	-----	--	--	--	--	------

[illegible]

Left Bank										
	Score >	1.2	0.85						Lt Bank CI >	1.13

Conditional Category	

00000	00	000	000	000	000
-------	----	-----	-----	-----	-----

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact 5.1	300	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category						
	Negligible	Minor	Moderate	Severe			
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.	
SCORE	1.5	1.3	1.1	0.9	0.7	0.5	1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.17

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 351

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/6/2022	Impact 5.1 Sec.	134	1

Name(s) of Evaluator(s)






Stream Name and Information					

Kristen Walls, WPIT, Emily Beacham, PE and Hannah Bullens

Stream Reach 5 - Impact Plate C1.5/Impact 5.1 Sec.

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Conditional Category	Count	Percentage
1	1	100%

	Optimal	Suboptimal	Marginal	Poor	Severe
Channel Condition	 <p>Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.</p>	 <p>Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.</p>	 <p>Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which</p>	 <p>Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent</p>	 <p>Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.</p>
Score	3	2.4	2	1.6	1

CI

1.6

NOTES>>

Banks inconsistent, some erosion present.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category

		Riparian Category						NOTE: Large trees approximately 40% canopy, small hardwoods below.
		Optimal	Suboptimal		Marginal		Poor	
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory . Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh >3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
			High	Low	High	Low	High	
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

NOTES>> Large trees approximately 40% canopy, small hardwoods below.

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.

3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Ensure the sums
of % Riparian
Blocks equal 100

Right Bank	% Riparian Area>	100%							100%		
	Score >	1.2									
Left Bank	% Riparian Area>	100%							100%	Rt Bank Cl >	1.20
	Score >	1.2								Lt Bank Cl >	1.20

Rt Bank CI >	1.20
Lt Bank CI >	1.20

CI

1.20

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle/pool complexes, stable features.

Conditional Category

Instream Habitat/ Available Cover	Optimal	Suboptimal	Marginal	Poor
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.
Score	1.5	1.2	0.9	0.5

NOTES>> Inconsistent water depths.

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact 5.1 Sec.	134	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered
					Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
	SCORE	1.5	1.3	1.1	0.9

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.10

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 147

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Instream Habitat/ Available Cover	Conditional Category			
	Optimal	Suboptimal	Marginal	Poor
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.
Score	1.5	1.2	0.9	0.5

CI

0.90

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact 5.2	131	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .
	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.				
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.05

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 138

CR = RCI X LF X IF

INSERT PHOTOS



DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/6/2022	Impact 5.3	155	1

Name(s) of Evaluator(s)	Stream Name and Information
Kristen Walls, WPIT, Emily Beacham, PE and Hannah Bullens	Stream Reach 5 - Impact Plate C1.5/Impact 5.3

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Young hardwoods.
Optimal	Suboptimal		Marginal		Poor			
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
		High	Low	High	Low	High	Low	
		Condition Scores	1.5	1.2 1.1	0.85 0.75	0.6 0.5		
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.							Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	100%					100%	
	Score >	0.85						
Left Bank	% Riparian Area>	100%					100%	
	Score >	0.85						
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.								
THE REACH CONDITION INDEX (RCI) >>								0.43
RCI= (Riparian CI)/2								
COMPENSATION REQUIREMENT (CR) >>								67
CR = RCI X LF X IF								

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Score	1.5	1.2	0.9	0.5
-------	-----	-----	-----	-----

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact 5.4	179	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category											
	Negligible		Minor		Moderate		Severe					
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.		Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.		20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.		40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered		60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered		Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.	
SCORE		1.5	1.3	1.1	0.9	0.7	0.5					

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.19

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

213

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/6/2022	Impact 5.5	206	1

Name(s) of Evaluator(s)	Stream Name and Information
Kristen Walls, WPIT, Emily Beacham, PE and Hannah Bullens	Stream Reach 5 - Impact Plate C1.5/Impact 5.5

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Young hardwoods.
Riparian Buffers	Optimal	Suboptimal	Marginal	Poor				
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
Condition Scores	1.5	High 1.2	Low 1.1	High 0.85	Low 0.75	High 0.6	Low 0.5	
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100		
Right Bank	% Riparian Area>	100%					100%	
	Score >	0.85						
Left Bank	% Riparian Area>	100%					100%	
	Score >	0.85						
CI= (Sum % RA * Scores*0.01)/2								
Rt Bank CI > 0.85								
Lt Bank CI > 0.85								
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 0.43

RCI= (Riparian CI)/2

COMPENSATION REQUIREMENT (CR) >> 89

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	3/25/2022	Impact 6.1	326	1

Name(s) of Evaluator(s)	Stream Name and Information
Kristen Walls, WPIT and Emily Beacham, PE	Stream Reach 6 - Impact Plate C1.6/Impact 6.1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
Score	3	2.4	2	1.6	1		3.0

NOTES>> No erosion present. Bank height <6 inches.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Easement located within portion of riparian buffer.
	Optimal	Suboptimal	Marginal	Low Marginal:	High Poor:	Low Poor:	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	20%	80%				100%
	Score >	1.1	0.75				
Left Bank	% Riparian Area>	30%	70%				100%
	Score >	1.1	0.75				

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				NOTES>> Lack of riffle pool, various velocities, silt substrate.	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	3/25/2022	Impact 6.1	326	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> Clear cut outside riparian buffer. Overgrown with briars.

	Conditional Category				
	Negligible	Minor	Moderate	Severe	
Channel Alteration	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered .
SCORE	1.5	1.3	1.1	0.9	0.7

0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.31

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

427

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/6/2022	Impact 7.1	363	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Eric Myers	Stream Reach 6 - Impact Plate C1.7/Impact 7.1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Erosion present on 40-60% of banks.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						Condition Scores	NOTES>> Riparian buffer left around stream, outside of buffer clear cut.
	Optimal	Suboptimal	Marginal	Poor	High	Low		
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
		High	Low	High	Low	High	Low	
	1.5	1.2	1.1	0.85	0.75	0.6	0.5	
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100		
Right Bank	% Riparian Area>	30%	70%				100%	
	Score >	1.5	0.85					
Left Bank	% Riparian Area>	30%	70%				100%	
	Score >	1.5	0.85					

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pool complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Varying velocities and substrates observed. Riffle-pool complexes present.

CI

1.50

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact 7.1	363	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No channel alteration.

	Conditional Category				
	Negligible	Minor	Moderate	Severe	
Channel Alteration	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .	60-100% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <i>recovered</i> .
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.21

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 439

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennia

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/6/2022	Impact 7.1 Sec.	83	1

Name(s) of Evaluator(s)






Stream Name and Information					

David Kwasniewski, PWD and Eric Myers

Stream Reach 6 - Impact Plate C1.7/Impact 7.1 Sec.

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Conditional Category

	Optimal	Suboptimal	Marginal	Poor	Severe
Channel Condition	 <p>Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.</p>	 <p>Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.</p>	 <p>Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which</p>	 <p>Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent</p>	 <p>Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.</p>
Score	3	2.4	2	1.6	1

CI

NOTES>>

40% of banks exhibiting erosion, particularly along outer meanders. Stream bed not covered by sediment.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category

Riparian Buffers	Optimal	Suboptimal		Marginal		Poor		Notes: Riparian buffer left around stream, outside of buffer clear cut.
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh >3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
			High	Low	High	Low	High	
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

**NOTES>> Riparian
buffer left around
stream, outside of buffer
clear cut.**

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.

Ensure the sums
of % Riparian
Blocks equal 100

Right Bank	% Riparian Area>	60%	40%					100%		
	Score >	1.5	0.85							
Left Bank	% Riparian Area>	30%	70%					100%	Rt Bank CI >	1.24
	Score >	1.5	0.85						Lt Bank CI >	1.05

NOTES>> Varying
velocites and substrates
observed. Riffle-pool
complexes present.

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle/pool complexes, stable features.

Conditional Category

Instream Habitat/ Available Cover	Optimal	Suboptimal	Marginal	Poor
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.
Score	1.5	1.2	0.9	0.5

CI

1.50

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact 7.1 Sec.	83	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No channel alteration.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.23

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 102

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	4/6/2022	Impact 8.1	132	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Eric Myers		Stream Reach 8 - Impact Plate C1.8/Impact 8.1						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Riparian buffer left around stream, outside of buffer clear cut.	
	Optimal	Suboptimal	Marginal	Poor					
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.		
	Condition Scores	1.5	High 1.2 Low 1.1	High 0.85 Low 0.75	High 0.6 Low 0.5				
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.									Ensure the sums of % Riparian Blocks equal 100
Right Bank	% Riparian Area>	20%	80%					100%	
	Score >	1.5	0.85						
Left Bank	% Riparian Area>	20%	80%					100%	
	Score >	1.5	0.85						
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH									
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.									
THE REACH CONDITION INDEX (RCI) >>								0.49	
RCI= (Riparian CI)/2									
COMPENSATION REQUIREMENT (CR) >>								65	
CR = RCI X LF X IF									

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Instream Habitat/ Available Cover	Conditional Category				changes, and shade present.
	Optimal	Suboptimal	Marginal	Poor	
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.	
Score	1.5	1.2	0.9	0.5	

C

1.2

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/25/2022	Impact 9.1	263	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category			
	Negligible	Minor	Moderate	Severe
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
				Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9
				0.7
				0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.44

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

379

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream






DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Unified Stream Methodology for use in Virginia

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/25/2022	Impact 9.1 Sec.	59	1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

	Optimal	Suboptimal	Marginal	Poor	Severe
Channel Condition	 <p>Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.</p>	 <p>Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (80-80%). Vegetative protection or natural rock prominent (80-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.</p>	 <p>Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute to stability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which</p>	 <p>Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent</p>	 <p>Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/draw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.</p>
Score	3	2.4	2	1.6	1

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

		Riparian Category						Notes: Mature forest canopy with hardwoods and pine.
		Optimal	Suboptimal		Marginal		Poor	
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
			High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

Right Bank	% Riparian Area>	100%							100%
	Score >	1.5							

[illegible]

Instream Habitat/ Available Cover	Conditional Category			
	Optimal	Suboptimal	Marginal	Poor
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.
Score	1.5	1.2	0.9	0.5

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/25/2022	Impact 9.1 Sec.	59	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-100% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
SCORE	1.5	1.3	1.1	0.9	0.7

SCORE **1.5** **1.3** **1.1** **0.9** **0.7** **0.5** **1.50**

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.44

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 85

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	3/25/2022	Impact 9.2	106	1

Name(s) of Evaluator(s)	Stream Name and Information
Kristen Walls, WPIT, Emily Beacham, PE	Stream Reach 9 - Impact Plate C1.9/Impact 9.2

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Incised intermittent channel with little access to flood plain. Minor erosion.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						Condition Scores	NOTES>> Mature forest with hardwoods present.
	Optimal	Suboptimal	Marginal	Poor	High Suboptimal:	Low Suboptimal:		
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable conditions.		
		High	Low	High	Low	High	Low	
	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

- Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
- Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
- Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	100%						100%
	Score >	1.5						
Left Bank	% Riparian Area>	100%						100%
	Score >	1.5						

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Not many leaf packs present.

CI

0.90

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	3/25/2022	Impact 9.2	106	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
					Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.26

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

134

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	3/25/2022	Impact 9.3	128	1
Name(s) of Evaluator(s)		Stream Name and Information						
Kristen Walls, WPIT, Emily Beacham, PE		Stream Reach 9 - Impact Plate C1.9/Impact 9.3						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Mature forest with canopy that includes pines and hardwoods.
Optimal	Suboptimal		Marginal		Poor			
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
		High	Low	High	Low	High	Low	
		Condition Scores	1.5	1.2 1.1	0.85 0.75	0.6 0.5		
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.							Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
Left Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH								
NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.								
THE REACH CONDITION INDEX (RCI) >>								0.75
RCI= (Riparian CI)/2								
COMPENSATION REQUIREMENT (CR) >>								96
CR = RCI X LF X IF								

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of fill material for disposal area.






Stream Assessment Form (Form 1)

Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	3/25/2022	Impact RR.1	123	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Eric Myers		Impact Plate C1.10/Impact RR.1						

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
Score	3	2.4	2	1.6	1		2.3

NOTES>> Channel does not have access to its floodplain. Erosion observed along outer meander and toe of slope. Herbaceous vegetation observed stabilizing bank as well as mature trees along banks.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Easement located within portion of riparian buffer.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	100%					100%
	Score >	1.5					
Left Bank	% Riparian Area>	100%					100%
	Score >	1.5					

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		0.90

NOTES>> Limited leaf pack in stream bed observed. No undercuts observed. Limited change in velocity. Cobbles were observed in the lower stretch of the reach.

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	3/25/2022	Impact RR.1	123	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category					
	Negligible	Minor	Moderate	Severe		
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7	0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.24

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

153

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.

Stream Assessment Form (Form 1)

Unified Stream Methodology for use in Virginia

For use in wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/25/2022	Impact RR.2	166	1






Name(s) of Evaluator(s)

David Kwasniewski, PWD and Eric Myers

Impact Plate C1.10/Impact RR.2

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Conditional Category

	Optimal	Suboptimal	Marginal	Poor	Severe
Channel Condition	 <p>Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.</p>	 <p>Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.</p>	 <p>Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which</p>	 <p>Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent</p>	 <p>Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.</p>
Score	3	2.4	2	1.6	1

CI

2.4

NOTES>>

Bedrock is present which is preventing downcutting.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category

		Riparian Category						Notes
		Optimal	Suboptimal		Marginal		Poor	
Riparian Buffers	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
			High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5	

NOTES>> Mature pine forest left and right bank. Hardwood understory present.

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.

Ensure the sums
of % Riparian
Blocks equal 100

Right Bank	% Riparian Area>	100%						100%		
	Score >	1.5								
Left Bank	% Riparian Area>	100%						100%	Rt Bank CI >	1.50
	Score >	1.5							Lt Bank CI >	1.50

Rt Bank CI >	1.50
Lt Bank CI >	1.50

CI

1.50

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle/pool complexes, stable features.

Conditional Category

Instream Habitat/ Available Cover	Optimal	Suboptimal	Marginal	Poor
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.
Score	1.5	1.2	0.9	0.5

NOTES>> Varying velocities were observed.

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/25/2022	Impact RR.2	166	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alteration has occurred within the reach.

	Conditional Category				
	Negligible	Minor	Moderate	Severe	
Channel Alteration	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.32

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>


219

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.

Unified Stream Methodology for use in Virginia

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	4/6/2022	Impact RR.3	149	1

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Conditional Category

NOTES>>	Little erosion observed. Stream has access to original flood plain.
---------	---

Conditional Category

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.	Ensure the sums
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.	of % Riparian
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.	Blocks equal 100

Right Bank	% Riparian Area>	100%							100%
	Score >	1.5							

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pool complexes, stable features.	NOTES>> Minimal flow; channel thalweg has a
---	--

NOTES>> Minimal flow;
channel thalweg has a
large amount of leaves.

DATE					
------	--	--	--	--	--

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	4/6/2022	Impact RR.3	149	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> Culvert pipe was observed in stream and actively conveying surface flows.

	Conditional Category				
	Negligible	Minor	Moderate	Severe	
Channel Alteration	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7

1.30

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.34

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

200

CR = RCI X LF X IF

INSERT PHOTOS



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.






Stream Assessment Form (Form 1)

Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/16/2022	Impact EW.1	124	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Emily Beacham, PE		Impact Plate C1.11/Impact EW.1						

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
Score	3	2.4	2	1.6	1		2.4

NOTES>> Well defined bed and bank, approximately 30% of banks are incised, bedrock was observed in the bed of channel to occupy approximately 90% of impact reach

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Easement located within portion of riparian buffer.
	Optimal	Suboptimal	Marginal	Low Marginal:	High Poor:	Low Poor:	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area>	50%	50%				100%
	Score >	1.5	0.85				
Left Bank	% Riparian Area>	30%	20%	50%			100%
	Score >	1.2	0.6	0.5			
						E	
						Rt Bank CI >	1.18
						Lt Bank CI >	0.73
							0.95

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		1.20

NOTES>> Channel observations leaf pack, changing velocities, woody debris. Stream would be shaded when leaves are on the trees.

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/16/2022	Impact EW.1	124	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No channel alteration was observed. Hwy 60 is located approximately 30 from the channel.

Channel Alteration	Conditional Category					
	Negligible	Minor		Moderate		Severe
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <u>recovered</u> .	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not <u>recovered</u> .	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7	0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >> 1.21

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >> 150

CR = RCI X LF X IF

INSERT PHOTOS:



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/16/2022	Impact EW.2	195	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Emily Beacham, PE	Impact Plate C1.11/Impact EW.2

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contribute to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>>	Point bars and benches are forming, minimal undercuts were observed in outermeandors
---------	--

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Regeneration area was observed outside of the forested area.
	Optimal	Suboptimal	Marginal	Poor	High	Low	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
		High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	60%	40%					100%
	Score >	1.2	0.85					
Left Bank	% Riparian Area>	50%	50%					100%
	Score >	1.2	0.85					

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				NOTES>> Undercutting was observed along the outer meandors, woody debris and leaf pack was observed in the stream channel. Stream would be shaded when leaves are on the trees.	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		

CI

CI

1.04

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/16/2022	Impact EW-2	195	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alteration observed.

Channel Alteration	Conditional Category					
	Negligible	Minor		Moderate		Severe
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40 - 60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60 - 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7	0.5

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.23

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

240

CR = RCI X LF X IF

INSERT PHOTOS:



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/18/2022	Impact EW.3	77	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniowski, PWD and Kristen Walls, WPIT	Impact Plate C1.11/Impact EW.3

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Relict benches observed. Stream channel had recent sediment accumulation in the channel bed.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						Condition Scores	NOTES>> Regeneration area was observed outside of the forested area along right bank.
	Optimal	Suboptimal	Marginal	Poor	High	Low		
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.	
	1.5	1.2	1.1	0.85	0.75	0.6	0.5	
<p>1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.</p> <p>2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.</p> <p>3. Enter the % Riparian Area and Score for each riparian category in the blocks below.</p>								
Right Bank	% Riparian Area>	40%	60%				100%	
	Score >	1.2	0.75					
Left Bank	% Riparian Area>	100%					100%	
	Score >	1.5						
								Rt Bank CI > 0.93
								Lt Bank CI > 1.50

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
	1.5	1.2	0.9	0.5		

NOTES>> Leaf pack and woody debris was observed within stream channel.

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/18/2022	Impact EW.3	77	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	Greater than 80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines AND/OR 80% of banks shored with gabion, riprap, or cement.
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.18

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

91

CR = RCI X LF X IF

INSERT PHOTOS:



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.

Stream Assessment Form (Form 1)






Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R3	02080205	3/18/2022	Impact EW.4	80	1

Name(s) of Evaluator(s)	Stream Name and Information
David Kwasniewski, PWD and Kristen Walls, WPIT	Impact Plate C1.11/Impact EW.4

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
	3	2.4	2	1.6	1		

NOTES>> Recent alluvium accumulation was observed in the channel bed. Stream velocity varies throughout reach.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Mostly hardwoods.
	Optimal	Suboptimal	Marginal	Poor	High Marginal	Low Marginal	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
		High	Low	High	Low	High	Low
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5

1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors.
2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below.
3. Enter the % Riparian Area and Score for each riparian category in the blocks below.

Right Bank	% Riparian Area>	100%						100%
	Score >	1.5						
Left Bank	% Riparian Area>	100%						100%
	Score >	1.5						

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				NOTES>> Grade controls with leaf pack were observed throughout reach. Minor undercuts were observed in the outer meanders.
	Optimal	Suboptimal	Marginal	Poor	
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.	
Score	1.5	1.2	0.9	0.5	

CI

E

Rt Bank CI >

Lt Bank CI >

CI

1.50

1.50

CI

1.20

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R3	02080205	3/18/2022	Impact EW.4	80	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.24

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

99

CR = RCI X LF X IF

INSERT PHOTOS:



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.






Stream Assessment Form (Form 1)

Unified Stream Methodology for use in Virginia

For use in Wadeable channels classified as intermittent or perennial

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R4	02080205	3/18/2022	Impact EW.5	239	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Kristen Walls, WPIT		Impact Plate C1.11/Impact EW.5						

1. Channel Condition: Assess the cross-section of the stream and prevailing condition (erosion, aggradation)

Channel Condition	Conditional Category					Score	CI
	Optimal	Suboptimal	Marginal	Poor	Severe		
							
	Very little incision or active erosion; 80-100% stable banks. Vegetative surface protection or natural rock, prominent (80-100%). AND/OR Stable point bars/bankfull benches are present. Access to their original floodplain or fully developed wide bankfull benches. Mid-channel bars, and transverse bars few. Transient sediment deposition covers less than 10% of bottom.	Slightly incised, few areas of active erosion or unprotected banks. Majority of banks are stable (60-80%). Vegetative protection or natural rock prominent (60-80%) AND/OR Depositional features contribute to stability. The bankfull and low flow channels are well defined. Stream likely has access to bankfull benches, or newly developed floodplains along portions of the reach. Transient sediment covers 10-40% of the stream bottom.	Often incised, but less than Severe or Poor. Banks more stable than Severe or Poor due to lower bank slopes. Erosion may be present on 40-60% of both banks. Vegetative protection on 40-60% of banks. Streambanks may be vertical or undercut. AND/OR 40-60% of stream is covered by sediment. Sediment may be temporary/transient, contribute instability. Deposition that contributes to stability, may be forming/present. AND/OR V-shaped channels have vegetative protection on > 40% of the banks and depositional features which	Overwidened/incised. Vertically/laterally unstable. Likely to widen further. Majority of both banks are near vertical. Erosion present on 60-80% of banks. Vegetative protection present on 20-40% of banks, and is insufficient to prevent erosion. AND/OR 60-80% of the stream is covered by sediment. Sediment is temporary/transient in nature, and contributing to instability. AND/OR V-shaped channels have vegetative protection is present on > 40% of the banks and stable sediment deposition is absent	Deeply incised (or excavated), vertical/lateral instability. Severe incision, flow contained within the banks. Streambed below average rooting depth, majority of banks vertical/undercut. Vegetative protection present on less than 20% of banks, is not preventing erosion. Obvious bank sloughing present. Erosion/raw banks on 80-100%. AND/OR Aggrading channel. Greater than 80% of stream bed is covered by deposition, contributing to instability. Multiple thread channels and/or subterranean flow.		
Score	3	2.4	2	1.6	1		2.0

NOTES>> Channel does not have access to the floodplain. Active erosion observed along outer meanders.

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Riparian Buffers	Conditional Category						NOTES>> Mostly hardwoods.
	Optimal	Suboptimal	Marginal	Poor	High Marginal	Low Marginal	
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and a non-maintained understory. Wetlands located within the riparian areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with > 30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh > 3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100	
Right Bank	% Riparian Area> 100%						100%
	Score > 1.5						
Left Bank	% Riparian Area> 100%						100%
	Score > 1.5						
						Rt Bank CI > 1.50	CI
						Lt Bank CI > 1.50	1.50

3. INSTREAM HABITAT: Varied substrate sizes, water velocity and depths; woody and leafy debris; stable substrate; low embeddedness; shade; undercut banks; root mats; SAV; riffle pools complexes, stable features.

Instream Habitat/ Available Cover	Conditional Category				Score	CI
	Optimal	Suboptimal	Marginal	Poor		
	Habitat elements are typically present in greater than 50% of the reach.	Stable habitat elements are typically present in 30-50% of the reach and are adequate for maintenance of populations.	Stable habitat elements are typically present in 10-30% of the reach and are adequate for maintenance of populations.	Habitat elements listed above are lacking or are unstable. Habitat elements are typically present in less than 10% of the reach.		
Score	1.5	1.2	0.9	0.5		1.20

NOTES>> Woody debris and leaf pack were observed. Varying gravel size in riffles. Case building (gravels) caddis fly larvae were observed in reach.

Stream Impact Assessment Form Page 2

Project #	Applicant	Locality	Cowardin Class.	HUC	Date	Data Point	SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility, LLC	Cumberland Co.	R4	02080205	3/18/2022	Impact EW.5	239	1

4. CHANNEL ALTERATION: Stream crossings, riprap, concrete, gabions, or concrete blocks, straightening of channel, channelization, embankments, spoil piles, constrictions, livestock

NOTES>> No alterations.

Channel Alteration	Conditional Category				
	Negligible	Minor	Moderate	Severe	
	Channelization, dredging, alteration, or hardening absent. Stream has an unaltered pattern or has naturalized.	Less than 20% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	20-40% of the stream reach is disrupted by any of the channel alterations listed in the parameter guidelines.	40-60% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.	60-80% of reach is disrupted by any of the channel alterations listed in the parameter guidelines. If stream has been channelized, normal stable stream meander pattern has not recovered.
SCORE	1.5	1.3	1.1	0.9	0.7

1.50

REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH

NOTE: The CIs and RCI should be rounded to 2 decimal places. The CR should be rounded to a whole number.

THE REACH CONDITION INDEX (RCI) >>

1.24

RCI= (Sum of all CI's)/5

COMPENSATION REQUIREMENT (CR) >>

296

CR = RCI X LF X IF

INSERT PHOTOS:



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.

Ephemeral Stream Assessment Form (Form 1a)

Unified Stream Methodology for use in Virginia

For use in ephemeral streams

Project #	Project Name	Locality	Cowardin Class.	HUC	Date	SAR #	Impact/SAR length	Impact Factor
2017-890	Green Ridge Recycling and Disposal Facility	Cumberland Co.	R6	02080205	3/18/2022	Impact EW.6	132	1
Name(s) of Evaluator(s)		Stream Name and Information						
David Kwasniewski, PWD and Kristen Walls, WPIT		Impact Plate C1.1/Impact EW.6						

2. RIPARIAN BUFFERS: Assess both bank's 100 foot riparian areas along the entire SAR. (rough measurements of length & width may be acceptable)

Conditional Category								NOTES>> Pinus taeda (80%) hardwoods (20%).		
Riparian Buffers	Optimal	Suboptimal		Marginal		Poor				
	Tree stratum (dbh > 3 inches) present, with > 60% tree canopy cover and an non-maintained understory. Wetlands areas.	High Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with 30% to 60% tree canopy cover and containing both herbaceous and shrub layers or a non-maintained understory.	Low Suboptimal: Riparian areas with tree stratum (dbh > 3 inches) present, with >30% tree canopy cover and a maintained understory. Recent cutover (dense vegetation).	High Marginal: Non-maintained, dense herbaceous vegetation with either a shrub layer or a tree layer (dbh > 3 inches) present, with <30% tree canopy cover.	Low Marginal: Non-maintained, dense herbaceous vegetation, riparian areas lacking shrub and tree stratum, hay production, ponds, open water. If present, tree stratum (dbh >3 inches) present, with <30% tree canopy cover with maintained understory.	High Poor: Lawns, mowed, and maintained areas, nurseries; no-till cropland; actively grazed pasture, sparsely vegetated non-maintained area, recently seeded and stabilized, or other comparable condition.	Low Poor: Impervious surfaces, mine spoil lands, denuded surfaces, row crops, active feed lots, trails, or other comparable conditions.			
			High	Low	High	Low	High		Low	
Condition Scores	1.5	1.2	1.1	0.85	0.75	0.6	0.5			
1. Delineate riparian areas along each stream bank into Condition Categories and Condition Scores using the descriptors. 2. Determine square footage for each by measuring or estimating length and width. Calculators are provided for you below. 3. Enter the % Riparian Area and Score for each riparian category in the blocks below.						Ensure the sums of % Riparian Blocks equal 100				
Right Bank	% Riparian Area>	100%						100%		
	Score >	1.5								
								CI= (Sum % RA * Scores*0.01)/2		
Left Bank	% Riparian Area>	100%						100%		
	Score >	1.5								
								Rt Bank CI >	1.50	CI
								Lt Bank CI >	1.50	1.50
REACH CONDITION INDEX and STREAM CONDITION UNITS FOR THIS REACH										

INSERT PHOTOS:



looking upstream



looking downstream



left bank looking downstream



right bank looking downstream

DESCRIBE PROPOSED IMPACT:

Placement of culvert pipe to convey surface flows for construction of roadway.